



SSA Atlantic  
A Cerberus Enterprise



PORTS AMERICA



## GSA SAFETY RULES AND GUIDELINES – CLERKS & CHECKERS

**“Work safely, orderly, and respectfully.”**

### **CLERKS AND CHECKERS - SAFETY BRIEFING**

1. Wear all PPE (Personal Protective Equipment)
2. Closed toed shoes must be worn at all time and steel toed safety shoes when working in the field.
3. Reflective safety vests must be worn when working in the field.
4. Hard Hats, safety vest and long pants must be worn when out of your vehicle anywhere in the vicinity of the ship to shore cranes.
5. Obey all driving rules when on the terminal (stop signs, speed limits etc.).
6. No Cell Phones, earpieces, blue tooth, etc. in work areas.
7. No smoking in company vehicles.
8. Return all company vehicles to the proper parking area.

### **DOCK MEN - SAFETY BRIEFING**

1. Wear all PPE (Personal Protective Equipment)
2. Hard hats, reflective safety vests, long pants and steel toed shoes are always worn.
3. Watch for traffic, never turn your back to oncoming traffic.
4. Stay in the designated safety lane when standing in the lead.
5. Never drive your POV under the cranes or in the leads.
6. No Cell Phones, earpieces, blue tooth, etc. in work areas.
7. No sitting on the crane.

### **DECK MEN - SAFETY BRIEFING**

1. Wear all PPE (Personal Protective Equipment)
2. Hard hats, reflective safety vests, long pants and steel toed shoes are always worn.
3. Notify superintendent with any unsafe conditions.
4. Stay three containers away from any live loads.
5. Watch for containers' movements from opposite end of the flagmen's' end. This will ensure the safety of any personnel from overhead dangers.
6. Ensure all lashers are working in pairs to avoid injury.
7. No Cell Phones, earpieces, blue tooth, etc. in work areas.
8. No chairs are allowed on the vessel.

**REPORT ANY UNSAFE CONDITION OR ACTIVITY**